

RESISTIVITY STATIONS AND DRILL LOGS, LINE 5, ENGINEER CREEK

Drill holes are 200 feet apart; Resistivity stations 100 feet apart. Holes drilled in 1922; Resistivity survey in 1952

Figure 15