

Table 1. Records of wells in the Anchorage area, Alaska--Continued

No.	Location	Owner	Driller	Date	Topographic situation	Altitude	Type ^{a/}	Depth (feet)	Diameter (in.)	Water level (feet)	Date	Yield (G.P.M.)	Draw-down (feet)	Use ^{b/}	Temp. (°F.)	Remarks
148	0.6 m. S. of Mountain View	Maj. Farmer	P. Brandl	1952	valley	147	Dr	68	6	-3	1952	T	...	
149	0.7 m. S. of Mountain View	J. Vanover	P. Brandl	1951	do	145	Dr	106	6	-10	1951	D	...	Supplies hog ranch.
150	Grandview Gardens	L. Varnell	Owner	1950	terrace	160	A	31	...	-26	1950	4	2	D	...	All sandy gravel.
151	Norené St., Grandview Gardens	Herb Kastner	P. Brandl	1952	do	161	Dr	84	6	-14	1952	D	...	Through till to gravel at 84 feet.
152	Opposite Anchor Homes on Otis Lake Rd.	USGS Test # 7	G. Ramsey	1952	do	129	Dr	396	8-6	-23.5	1952	see log	...	Ab	...	Temperature at 210 ft.
153	N. end Anchor Homes on Otis Lake Rd.	USGS Test # 6	C. Chausse	1951	do	129	Dr	82	7	-23.73	9/29/51	19 1/2	7.6	Ab	...	Gravel encountered at 74
154	Opposite Anchor Homes on Otis Lake Rd.	R. Kessler	G. Ramsey	1951	do	128	Dr	77	6	-22	1951	10	10	D	...	
155	One-fourth mi. SW of Otis Lake	McInnes			hilltop	190?	Dg	27	...	-22	1951	D	...	Struck till at 27 ft.
156	Green Acres, Otis Lake Rd.	Arthur Johnson	G. Camp	1952	hillside	164	Dr	43	6	-31		13	...	D	...	All sand and gravel.
157	Do	R. Burge	Owner		Valley floor	148	Dg	16	...	-13	10/11/50	7	...	T	...	All sand and gravel.
158	Do	M. Hopkins	S. Kosloski	1952	do	148	Dr	140	6	-5 1/2	1952	25	11 1/2	D	...	
159	Otis Lake & Tudor Rds.	Cottonwood Courts	H. Stone	1951	do	171	Dr	54	6	-21	1951	T	...	
160	Otis Lake Rd. S. of Campbell Creek	R. W. Gordon	Owner	1950	do	170	A	14	12	-9.1	10/11/50	D	...	All sand and gravel.
161	Otis Lake Rd., S. of Campbell Creek	Hufeisen housing project	J. Merrington	1952	ridge	189	Dr	182	8	-32.2	10/14/52	70±	28±	M	...	cf. wells 158, 1952, 147, 102, 181
162	Off Boniface Rd., SW of Russian Jac Springs	E. J. Banta	Owner	1949	Valley floor	206	Dg	29	...	-26	1952	D	...	
163	Do	B. B. Collins	R. Miller	1951	do	204	Dr	96	6	-31	1951	D	...	
164	Do	W. J. Vaudrin	do	1951	gentle slope	210	Dr	45	4	-11	1951	D	...	
165	N. of Dog Pound, Le Barr Rd.	I. Walker	Owner		hilltop	260	Dg	40	42	-37	1950	D	...	
166	N. end of Baxter Rd.	H. Moline	L. Schackle	1952	gentle slope	219	Dr	83	6	-38	1952	20	38	D	...	Water contains iron.
167	Tudor & Muldoon Rds.	G. Schwartz	Owner	1950	ridge	223	Dg	47	36	-44	10/9/50	D	...	Well in till, yield inadequate.
168	Do	Do	G. Ramsey	1951	do	323	Dr	81	6	-61	1951	D	...	Water contains iron, but is improving with use.
169	Muldoon Rd., .8 m. S. of LeBarr Rd.	W. M. Lewis	Owner		hilltop		Dg	28	36	-19.6	10/9/50	D	...	All sand and gravel.
170	Dobin Rd., off Muldoon Rd.	F. Toomey	L. Schackle	1952	do	315	Dr	177	6	-79.5	10/9/52	12	8	D	...	cf. well 166.
171	Muldoon Rd., 1/2 mi. S. of Oilwell Rd.		L. Nigle	1952	valley floor	264	Dr	32	6	-7	7/17/52	D	...	Through gravel to till at 30 feet.
172	Oilwell Rd., nr.	U. S. Army	J. Merrington	1952	terrace	199	Dr	157	6	-5.05	8/27/52	60	3.5	D	...	Five ft. of #60 slot screen installed.