

SECTION

1. Martin bed at locality U.
2. Martin bed in Evan Jones crosscut tunnel.
3. Martin bed 300 feet west of new Eska tunnel in north-limb workings.
4. Shaw bed at locality U.
5. Shaw bed in Evan Jones crosscut tunnel.
6. Shaw bed 750 feet west of new Eska tunnel in north-limb workings.
7. Eska bed at locality U.
8. Eska bed in Evan Jones crosscut tunnel.
9. Eska bed in Eska mine, west of Eska fault zone.
10. Bed 8 at locality O.
11. Bed 8 in No. 68 airway near top, 4,000 feet west of Evan Jones tunnel.
12. Buffalo bed 2 at locality Q.
13. Bed 6(?) at locality Q.
14. Bed 6 in Evan Jones mine, 2,000 feet west of crosscut tunnel.
15. Bed 5 at locality Q.
16. Bed 5 at locality U.
17. Bed 5 in Evan Jones mine, 2,000 feet west of crosscut tunnel.
18. Premier coal group at locality O.
19. Beds 2(?) and 3(?) at locality N.
20. Beds 2(?) and 3(?) at locality X.
21. Beds 2(?) and 3(?) in W1/2 SE1/4 NW1/4 sec. 16.
22. Bed 4(?) in W1/2 SE1/4 NW1/4 sec. 16.

Figure 5.– Sections of coal beds in eastern part of lower Matanuska Valley coal field.