



MAXIMUM ESTIMATED TSUNAMI INUNDATION FOR AKHIOK, ALASKA

The State of Alaska makes no expressed or implied warranties (including warranties for merchantability and fitness) with respect to the character, functions, or capabilities of the electronic data or products or their appropriateness for any user's purposes. In no event will the State of Alaska be liable for any incidental, indirect, special, consequential, or other damages suffered by the user or any other person or entity whether from the use of the electronic services or products or any failure thereof or otherwise. In no event will the State of Alaska's liability to the Requestor or anyone else exceed the fee paid for the electronic service or product.

Publications produced by the Division of Geological & Geophysical Surveys (DGGS) are available for download from the DGGS website (dggs.alaska.gov). Publications on paper or digital media can be examined or purchased in the Fairbanks office:

STATE OF ALASKA



DEPARTMENT OF NATURAL RESOURCES DIVISION OF GEOLOGICAL & GEOPHYSICAL SURVEYS 3354 College Road ♦ Fairbanks, Alaska 99709-3707 Phone 907-451-5010 ♦ Fax 907-451-5050



Alaska Earthquake Center Geophysical Institute University of Alaska Fairbanks PO Box 757320, Fairbanks, Alaska 99775-7320 email: uaf-aec@alaska.edu

website: https://earthquake.alaska.edu/tsunamis

E.N. Suleimani¹, J.B. Salisbury², and D.J. Nicolsky¹ SCALE 1:6000 0.13 0.5 MILE 0.5 KILOMETER 1000 FEET TRINITY ISLANDS MAP LOCATION 155°W 154°W LOCATION OF MAP AREA

Projection:

Base map from: ESRI World Imagery, Maxar

Alaska State Plane Zone 5 (Feet)

Datum: North American Datum of 1983 Cartography by: L. Gardine¹ (2021) Cartographic review by: A.E. Macpherson² (2021) Review by: R. Thomson³ (2020)

R. von Huene⁴ (2020)

Affiliations:

Alaska Earthquake Center,

Geophysical Institute, University of Alaska Fairbanks,

PO Box 757320, Fairbanks, AK 99775-7320 ² Alaska Division of Geological & Geophysical Surveys, 3354 College Rd, Fairbanks, Alaska 99709-3707

³ Institute of Ocean Sciences, 9860 West Saanich Rd Suite 1101, Sidney, BC V8L 5H5 Canada

⁴ U.S. Geological Survey, 350 N. Akron Road, Moffett Field CA 94035

This report was funded by the U.S. Department of Commerce/National Oceanic and Atmospheric Administration (NOAA) through National Tsunami Hazard Mitigation Program Award NA20NWS4670057 and NA19NWS4670008 to the Alaska Division of Homeland Security and Emergency Management. This does not constitute an endorsement by NOAA.