

August 10, 1938

PE-85-10

Plate No.1

Sketch of
Surface Workings
Vicinity of
Gold Dust Fault
JAF PROPERTY
Willow Creek
Willow Creek District
Alaska

Owners,
E. Swetman & Associates

Sketch by,
J. C. Roehm
Associate Engineer

North

Strike of Fault --- N.15°W.

Gold
Dust

Fault

Zone

4240'

4160'

Tunnel No.4

Vein exposed 50'
6 to 8" Banded quartz

Vein not exposed
on surface

700' to
Tunnel No.5

Tunnel No.3

Camp 2000'

Cuts on vein

Vein quartz 12 to 30" Wide

4080'

Tunnel No.1

4000'

Tunnel No.2

Quartz Float in creek
shows gold