

Table 1. Records of wells in the Anchorage area, Alaska--Continue

No.	Location	Owner	Driller	Date	Topographic situation	Altitude	Type ^a /	Depth feet)	Diameter (in.)	Water level (feet)	Date	Yield (G.P.M.)	Draw- down (feet)	Use ^b /	Temp. (°F.)	Remarks
75	45 Gerans Way, nr. McRae Rd.	L. H. Norene	L. Schachle	1952	dissected terrace	63	Dr	244	6	-40	1952	20	18	D	...	Pea gravel encountered at 237 feet.
76	Gerans Way, nr. Spenard Rd.	C. Kordus	P. Brandl	1951	do	85	Dr	116	6	-33	1951	D	...	
77	Spenard Rd., E. of Fish Creek	A. Woodward	Owner	1950	do	...	Dg	32	22	-27.5	1950	T	...	Yield small.
78	Spenard Rd., W. of Fish Creek	Grizzly Trailer Court	G. Ramsey	1951	hillside	64	Dr	83	6	-19 1/2	1951	10	3 1/2	T	...	Yield by bailing.
79	Spenard Rd., E. of road forks	J. Hurst	Owner	1952	do	88	Dr	60	4	-28	1952	D	...	
80	Road forks, NE of Lake Spenard	*Lake Motel	J. Merrington	1952	terrace	72	Dr	278	8	-8	1952	40	-54	T	...	Yield by bailing.
81	Nr. east shore of Lake Spenard	W. W. Fultz	J. Merrington	1952	slope	67	Dr	67	8	-22.54	6/4/52	40	10	T	...	cf. wells 90 and 93
82	East shore of Lake Spenard	Idle Hour Country Club		1946	lake shore	81	Dg	16 1/2	46	-10.4	9/12/52	R	38	
83	Southwest shore of Lake Hood	10th Rescue Detachment		1946	do	72	Dr	162	6		25	...	D	...	
84	NE end of air field	Northern Consolidated	L. Schachle	1952	Terrace		Dr	132	6		15	58	D	...	
85	Do	Alaska Airlines	J. Currie	1951	do	81	Dr	158	6		35	6	
86	Nr. Control tower	International Airport	J. Currie	1950	do	88	Dr	308	6	Yield poor. Has #10 slot screen installed.
87	S. end of air field	International Airport	J. Currie	1949	do	110	Dr	155	6	-90	1950	22	
88	International Airport & Sand Lake Rds.	International Trailer Park	G. Kosloski	1952	do	76	Dr	213	6	-63.30	7/23/52	cf. well 89.
89	On DeLong Lake, Sand Lake Rd.	Snyder	J. Merrington	1951	lake shore	79	Dr	215	6	-40	1951	20	90	D	...	cf. well 88.
90	Sand Lake Rd., E. of DeLong Lake	D. Clover	G. Ramsey	1951	hill	100	Dr	317	6	-55	1951	20	26	D	...	cf. wells 89 and 93
91	Sand Lake Rd. & Raspberry Rd.	L. Onstatt	Owner	1950	hillside	138	A	50	7	-48	1950	D	...	Yield small.
92	Raspberry Rd.	Imlac			rolling ground	97	Dr	44	3	D	...	Water from hardpan. Yield meager.
93	NE. shore of Sand Lake	E. Crawford	G. Ramsey	1951	hillside	106	Dr	318	6	-63	11951	8	15	D	...	cf. wells 89 and 90.
94	Strawberry Rd.	L. F. Burke	Owner	1950	rolling ground	125	Dg	34	24	-30	1950	5	2	D	35	
95	Strawberry Rd.	E. Nelson		1950	hillside	122	Dg	26	42	-23	1950	D	37	Yield small.
96	Sand Lake Rd., 0.6 m. S. of Strawberry Rd.	H. McClure	Owner	1949	do	...	Dg	21	24	-18	1950	D	...	Yield small.
97	2 3/4 m. SW of Lake Spenard.	A. C. S.			hilltop	140	Dr	205	6	-155	1950	29	...	D	35	Quality poor.
98	Do	do	J. Merrington	1952	do	140	Dr	240	6	-115	7/17/52	70	4	D	...	5 ft. 65-slot screen installed.