

SCENERY LAKE DAM SITE
(MILE 3.6)

EXPLANATION

- Quartz diorite
- Plagioclase gneiss
- Indefinite contact
- Concealed contact
- Linears determined from aerial photographs



Section along line A-A'



Section along line B-C-D-E-F



Section along line A-B-C-D (see plate 2)