



Fig. 22.--Geologic cross sections at bridge at Mile Post 458.4 in Goldstream Valley, Fairbanks, Alaska
The Alaska Railroad

This report is preliminary and has not been edited or reviewed for conformity with U.S. Geological Survey standards and nomenclature.