

Report
QIE
75
065
no. 60-11




Fig. 25.--Geologic cross section at bridge at Mile Post 460.4 over Goldstream Creek near Fairbanks, Alaska

The Alaska Railroad

This report is preliminary and has not been edited or reviewed for conformity with U.S. Geological Survey standards and nomenclature.