


DILLINGHAM, ALASKA - EROSION MONITORING SITES


Sewage Lagoon Site



0 50 0 250
m ft







2017 Imagery

Credits: Aerial Imagery provided by DGGs



0 3 km
0 2.5 mi

Legend

-  Camera
-  Stake
-  Coastal Profile
-  Vegetation Line (2016)
-  Vegetation Line (2017)
-  Vegetation Line (2018)

