

X-RAY DIFFRACTION, X-RAY FLUORESCENCE, PYROLYSIS, SOURCE ROCK ANALYSIS, 2D SEM IMAGES FROM CUTTINGS FOR WELLS: MALGUK 1, MERAK 1, PIPELINE STATE 1, WEST KAVIK 1, AND WOLFBUTTON 25-6-9

Contributions by Dan Creighton¹

Geologic Materials Center Data Report 469

GMC data reports provide analytical and interpretive data resulting from testing by third parties on material borrowed from samples housed at the Alaska Geologic Materials Center. These files are produced by the third-party agency or company that conducted the sampling and analysis. The results and interpretations have not undergone technical review and should not be cited as reviewed data or as an authoritative information source.

July 2020
STATE OF ALASKA
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF GEOLOGICAL & GEOPHYSICAL SURVEYS
GEOLOGIC MATERIALS CENTER



¹ Burgundy Exploration and Halliburton

