

Table 1. Records of wells in the Anchorage area, Alaska--Continued

No.	Location	Owner	Driller	Date	Topographic situation	Altitude	Type	Depth (feet)	Diameter (in.)	Water level (feet)	Date	Yield (G.P.M.)	Draw-down (feet)	Use b/	Temp. (°F.)	Remarks
99	W. Strawberry Rd., .8 m. W. North Jewel Lake Rd.	Steinhauser	S. Chapman	1952	hillside	187	Dr	285	6	-164	1952	8	...	D	...	Blue silt to 283; small gravel 283-285.
100	W. Strawberry Rd., .5 m. W. of North Jewel Lake Rd.	L. C. Johnson	J. Currie		hilltop	230	Dr	165	6	-157	.....	...	...	Ab	...	
101	North Jewel Lake Rd., nr. West Strawberry Rd.	I. Iverson	R. Miller	1948	hillside	104	Dr	96	5	-85	1948	8	1	D	36	
102	North Jewel Lake Rd., nr. W. Raspberry Rd.	J. Peterson			do	148	Dr	154	...	-120		...	...	D	...	
103	Jewel Lake Road, south of gravel pits	Sea View Heights	R. Miller	1950	cliff	163	Dr	220	4	-150	1950	...	...	Ab	...	Silty water.
104	W. shore of Jewel Lake	R. Risch	Owner	1950	shore	...	A	43	9	-42.26	10/5/50	...	...	D	35	
105	Jewel Lake Rd., 1.2 m. W. of Alaska Railroad	J. Gilliland	do	1949	hillside	90	Dg	18	8	-13	1950	...	...	D	...	Yield meager.
106	Jewel Lake Rd., .5 m. W. of Alaska Railroad	J. Theus	do	1951	do	86	Dg	14	48	-11	1952	...	...	D	...	Till at 10 ft.
107	Potter Rd., at Fireweed Lane	Sterling Service Station	G. Ramsey	1951	terrace	112	Dr	113	6	-9	1951	30	...	D	...	
108	Potter Rd., 1 m. S. of Fireweed Lane	E. E. Potter	J. Condell	1947	hillside	133	Dg	27	30	-25	1950	...	...	D	...	Yield is small.
109	Do	Van Huss	G. Ramsey	1951	do	119	Dr	82	6	+		...	...	D	...	Encounters sand below till at 81 ft.
110	Chugach storage yard, off Campbell Sta. Rd.	USGS Test #2	C. Chausse	1951	terrace	94	J	118	4	-7.42	6/21/51	...	...	Obs.	...	
111	Do	USGS Test #3	do	1951	do	94	J	20	3	-11.32	6/21/51	15	5.4	Obs.	35	Not entirely clear of sil
112	Potter Rd., at Dowlins Rd.	Hilltop Trailer Court	G. Camp	1952	Knoll	135	Dr	113	6	-6	1952	25	72	T	...	
113	Dowlins Rd., at Potter Rd.	Potter Road Tourist Camp	J. March	1950	do	120	Dr	34	6	-3	1951	...	...	T	...	Yield small.
114	Dowlins Rd., .7 mi. W. of Potter Rd.	S. Chapman	S. Chapman	1952	slope	126	Dr	93	6	+3	10/15/52	...	...	D	...	
115	Potter Rd., .5 m. S. of Dowlins Rd.	C. R. Underwood	S. Alward	1949	terrace	135	Dg	21	36		10/4/50	...	...	D	...	Yield small. Water from sand lens in till.
116	Potter Rd., .6 mi. S. of Dowlins Rd.	H. Johnson	S. Chapman	1952	do	132	Dr	86	6	-7.21	10/20/50	...	...	D	...	
117	Potter Rd., .3 m. N. of Wells Rd.	E. Zurian	L. Nigle	1952	gentle slope	119	Dr	35	6	-12.90	8/6/52	...	...	T	...	
118	Do	Yucca Club	do Brandl	1952	do	120	Dr	39	6	.....		...	...	R	...	
119	Do	Ace in the Hole	S. Kosloski	1951	do	120	Dr	102	6	+5+	1952	...	...	R	...	Water is hard.
120	Potter Rd., .7 m. S. of Wells Rd.	O. J. Sasse	Owner		Knoll	148	Dg	16	36	.....		...	...	D	...	Ample supply.
121	O'Malley Rd., 2.1 mi.	M. Evans	G. Ramsey	1951	hillside	382	Dr	175	6	-145	1951	7 / 2	20	D	...	