



Fig. 17.--Geologic cross sections at bridge at Mile Post 456.7 in Goldstream Valley near Fairbanks, Alaska. The Alaska Railroad.

This report is preliminary and has not been edited or reviewed for conformity with U.S. Geological Survey standards and nomenclature.